



## TEMPLE MOUNTAIN ENERGY, INC.

"Providing Enhanced Oil Recovery Technologies"

cc: Paul  
Daron  
M0470036  
TaskID# 1664

4526 Ridgeview Dr.  
Eagan, MN 55123  
Phone (651) 452-7125  
Fax (651) 905-1998  
12<sup>th</sup> December 2006

Department of Natural Resources  
Division of Oil, Gas & Mining.  
1594 West, North Temple.  
Suite 1210, PO Box 145801  
Salt Lake City  
Utah  
84114-5801

For the Attention of; - Paul B. Baker.

In respect of; - Cessation Order No. MC2006-03-14-01

Dear Sirs,

Further to the above mentioned notice and our subsequent discussions with you we hereby attach our drawings and associated GPS logs for the small mine permit area as requested.

In addition to the supply of the requested information we would like to reiterate that due to the proximity of previous operations, abandoned materials and equipment, along with the impact from previous operators exploratory works as well as public access issues it was never the intention of TME Inc or TME AR LLC to encroach beyond the permitted 5 acre small mine area.

It is our intention however to be responsible for all our operational areas nationally or internationally as we are committed to ensuring minimal impact on the environment. TME has endeavored to remove and tidy the adjacent impacts and abandonment's in close proximity to our operation, to reduce overall residual risk and to improve the visual amenity of our works. Along with this we have had to manage public ingress and access through the mine site for others using the pre-existent and pre- installed roadways.

As demonstrated TME had instigated a reclamation plan to include some of these areas and that created by our own establishment operations, and as discussed we will complete the sub-soil works prior to the Christmas Holiday period and electronically transmit the photographs of such prior to topsoil replacement. The topsoil operation and seeding will be completed concurrently to ensure loose placement as instructed, this will commence as the weather conditions permit.

As reviewed at our meeting on site the health, safety and environmental violations concerned us greatly and we would like to assure you and your colleagues the TME board will does not take these issues lightly and will ensure all future compliances as a matter of course.


Jim Runquist  
CEO Temple Mountain Energy Inc.

RECEIVED

DEC 26 2006

DIV. OF OIL, GAS & MINING





RECEIVED

DEC 26 2007


DIV. OF OIL, GAS & MINING



TME Mine mapping Co-ordinates.  
GPS 11th Dec 2006

Waypoint	33	N40 20.12	5050 ft
Waypoint	34	N40 20.11	5052 ft
Waypoint	35	N40 20.12	5046 ft
Waypoint	36	N40 20.12	5046 ft
Waypoint	37	N40 20.11	5033 ft
Waypoint	38	N40 20.12	5041 ft
Waypoint	39	N40 20.13	5049 ft
Waypoint	40	N40 20.14	5044 ft
Waypoint	41	N40 20.16	5036 ft
Waypoint	42	N40 20.18	5044 ft
Waypoint	43	N40 20.19	5058 ft
Waypoint	44	N40 20.20	5057 ft
Waypoint	45	N40 20.19	5053 ft
Waypoint	46	N40 20.19	5049 ft
Waypoint	47	N40 20.19	5042 ft
Waypoint	48	N40 20.18	5052 ft
Waypoint	49	N40 20.17	5051 ft
Waypoint	50	N40 20.15	5034 ft
Waypoint	51	N40 20.13	5038 ft





Office and Workshop

Mine Deposit

Current Reclamation (1.2 ac)

Previous Reclamation (1.6 ac)

Original Highway 45 and current access road

Pre existing tracks and access routes

Equipment and Process area

Operational Mine roadway

Topsoil Storage



Mine Boundary (5.3 ac)

## Notes

No Overburen storage designated as previously stripped by other, location unknown. Current overburden being used to reclaim previous and TME used areas.

TME Asphalt Ridge LLC.





Notes

No Over-burn storage is designated for the pilot program as this was previously stripped by others, location unknown. Current overburden being used to reclaim previous use and TME used areas.

RECEIVED

DEC 26 2006

DIV. OF OIL, GAS & MINING

TME Asphalt Ridge LLC. 5 Acre Small Mine.